

PLUG		JACK																																											
	<table border="1"> <thead> <tr> <th>LETTER</th> <th colspan="2">INCHES [MILLIMETERS]</th> </tr> <tr> <th></th> <th>MINIMUM</th> <th>MAXIMUM</th> </tr> </thead> <tbody> <tr> <td>A</td> <td>.1783 [4.53]</td> <td>.1807 [4.59]</td> </tr> <tr> <td>B</td> <td>.1147 [2.91]</td> <td>.1154 [2.93]</td> </tr> <tr> <td>C</td> <td>.0354 [0.90]</td> <td>.0366 [0.93]</td> </tr> <tr> <td>D</td> <td>.060 [1.52]</td> <td>.070 [1.78]</td> </tr> <tr> <td>E</td> <td>.092 [2.34]</td> <td>.096 [2.44]</td> </tr> </tbody> </table>	LETTER	INCHES [MILLIMETERS]			MINIMUM	MAXIMUM	A	.1783 [4.53]	.1807 [4.59]	B	.1147 [2.91]	.1154 [2.93]	C	.0354 [0.90]	.0366 [0.93]	D	.060 [1.52]	.070 [1.78]	E	.092 [2.34]	.096 [2.44]		<table border="1"> <thead> <tr> <th>LETTER</th> <th colspan="2">INCHES [MILLIMETERS]</th> </tr> <tr> <th></th> <th>MINIMUM</th> <th>MAXIMUM</th> </tr> </thead> <tbody> <tr> <td>F</td> <td>.208 [5.28]</td> <td>.212 [5.38]</td> </tr> <tr> <td>G</td> <td>.181 [4.60]</td> <td>.183 [4.65]</td> </tr> <tr> <td>H</td> <td>.1146 [2.91]</td> <td>.1154 [2.93]</td> </tr> <tr> <td>I</td> <td>.0496 [1.26]</td> <td>.0504 [1.28]</td> </tr> <tr> <td>J</td> <td>.075 [1.91]</td> <td>.077 [1.96]</td> </tr> </tbody> </table>	LETTER	INCHES [MILLIMETERS]			MINIMUM	MAXIMUM	F	.208 [5.28]	.212 [5.38]	G	.181 [4.60]	.183 [4.65]	H	.1146 [2.91]	.1154 [2.93]	I	.0496 [1.26]	.0504 [1.28]	J	.075 [1.91]	.077 [1.96]
LETTER	INCHES [MILLIMETERS]																																												
	MINIMUM	MAXIMUM																																											
A	.1783 [4.53]	.1807 [4.59]																																											
B	.1147 [2.91]	.1154 [2.93]																																											
C	.0354 [0.90]	.0366 [0.93]																																											
D	.060 [1.52]	.070 [1.78]																																											
E	.092 [2.34]	.096 [2.44]																																											
LETTER	INCHES [MILLIMETERS]																																												
	MINIMUM	MAXIMUM																																											
F	.208 [5.28]	.212 [5.38]																																											
G	.181 [4.60]	.183 [4.65]																																											
H	.1146 [2.91]	.1154 [2.93]																																											
I	.0496 [1.26]	.0504 [1.28]																																											
J	.075 [1.91]	.077 [1.96]																																											
<b>SPECIFICATIONS</b>		<b>CABLE GROUPS</b>																																											
<b>ELECTRICAL SPECIFICATIONS</b> IMPEDANCE: 50 Ω WORKING VOLTAGE RATING: 250 VRMS FREQUENCY RANGE: 0-40 GHZ		<b>GRP FOR THESE CABLE TYPES</b>																																											
<b>MECHANICAL SPECIFICATIONS</b> MATING: .250 - 36 THREAD DURABILITY: 500 CYCLES MINIMUM CABLING: SOLDER		SR1 .085 SEMI RIGID; RG-405/U; BELDEN 1671A; RD-179																																											
<b>PLATING</b> G - GOLD	<b>DIELECTRIC MATERIAL</b> NOB - NORYL OXIDE® BEAD	FOR A MORE EXTENSIVE LISTING OF CABLE GROUPS, PLEASE REFER TO PAGES 134-145																																											



FIG. 1  
RF29M-SR1

PHOTOS FOR REFERENCE ONLY, SHOWN AT 200% ACTUAL SIZE.

FOR MOUNTING CONFIGURATIONS REFER TO PAGES 149-164

PART #	FIG	DESCRIPTION	CBL GRP	NOTES	PLATING		
					BDY	P/C	DIE
RF29M-SR1	1	PLUG	SR1	DIRECT SOLDER	G	G	NOB

## SEMI-RIGID CABLE SOLDERING TIPS

- Always avoid excessive heat when soldering.
- Use an active flux such as Kester #2331 when soldering semi-rigid cable to nickel-plated connector bodies.
- Fixture cable and solder ferrule or cable and connector body firmly when soldering to the jacket of semi-rigid cable.
- Work rapidly during soldering operations and cool the new joints by brushing with alcohol.
- Carefully follow the semi-rigid cable manufacturer's instructions for cable thermal cycling procedures.